

## Refurbishment Horizontal Split Case Pump

**WORTHINGTON PUMP 12LNV29 DRIVEN BY  
SIEMENS 1500KW SLIP RING MOTOR**



*Corrosion Caused  
By Improper Gasket Cutting*



## *Refurbishment Horizontal Split Case Pump*

**WORTHINGTON PUMP 12LNV29 DRIVEN BY  
SIEMENS 1500KW SLIP RING MOTOR**

