

Rebuild Vibration & Rejected Pump

(THE FAILURE PUMP CAUSED BY CASING OFFSET)



Replace New Part for Corrossion casing



Offset Casing Part



Sungai Muar (Grisek) Weir Pump